



POLE FRAMING SLACK-SPAN DEAD-END



GUY ATTACHMENT 5/16" PRE-FORM DEAD END **BONDING CLAMP** GALV. STAPLES %₆" STRAND 5/16 " GUY STRAND



DESCRIPTION


THIMBLE EYE BOLT

SQUARE WASHER


SQUARE NUT

SUSPENSION CLAMP

POLE FRAMING LINE POLE DEAD-END **COMBINATION No. 1**



ASSEMBLED VIEW



DESCRIPTION

SUSPENSION CLAMP

5/16" PRE-FORM DEAD END

%" MACHINE BOLT

SQUARE WASHER

GUY ATTACHMENT

BONDING CLAMP

GALV. STAPLES


5/16" GUY STRAND

5/16" STRAND

SQUARE NUT

EYE NUT

POLE FRAMING DEAD-END COMBINATION No.2



ASSEMBLED VIEW

DESCRIPTION

%" MACHINE BOLT

SUSPENSION CLAMP SQUARE NUT

SQUARE WASHER

½" x 3½" MACHINE BOLT

5/16" STRAND


SUSPENSION CLAMP (2 HOLES)

POLE FRAMING **CROSS - OVER POLE**

<u>ITEM</u> **DESCRIPTION**

EXPLODED VIEW


- %" MACHINE BOLT
 - SUSPENSION CLAMP
- SQUARE NUT SQUARE WASHER CARRIAGE ARM BRACE
- %" x 3" LAG SCREW
- WOOD ARM 5/46"" STRAND
- CARRIAGE BOLT WITH WASHER (ROUND)



EXPLODED VIEW

POLE FRAMING WOOD CROSS-ARM

DESCRIPTION %" MACHINE BOLT SUSPENSION CLAMP SQUARE NUT SQUARE WASHER 5/16" STRAND METAL CROSS ARM ½" x 3" LAG SCREW




EXPLODED VIEW

CABLE PLACING ADJUSTABLE EXTENSION ARM

- 1. CHECK BONDING REQUIREMENTS ALL POLES THIS SHEET.
- 2. ASSEMBLIES SHOWN ON THIS SHEET NOT DRAWN TO SCALE.

The selection and use of this Standard Drawing, while designed in accordance with generally accepted engineering principles and practices, is the sole responsibility of the user.



Standard Drawing Title

CABLE PLACEMENT AND WOOD POLE FRAMING DETAILS (2 OF 3)

All material and workmanship shall be in accordance with the City of Portland Standard Construction Specifications.

Effective Date: 03-21-12

Calc. Book No.:

Standard Drawing No.

Baseline Report Date:

P-636